




Panther Ausf. G Cuckoo (4th Battalion, Coldstream Guards, 1944–45) Zimmerit damage on glacis plate

The grey area indicates the part covered in Zimmerit, which had chipped off the upper centre area between the machine gun ball mount and driver's periscope.

Print out at: —

<i>Scale</i>	<i>Percentage</i>	<i>Document size</i>
1:35	100%	10.0 × 13.0 cm
1:16	219%	21.9 × 28.5 cm
1:72	48.6%	4.9 × 6.3 cm
1:76	46.1%	4.6 × 6.0 cm
1:87	40.2%	4.0 × 5.2 cm

© 2025 Jakko Westerbeke <jakko@xs4all.nl>. This file may be distributed under the terms of the Creative Commons Attribution-ShareAlike 4.0 International licence (CC BY-SA 4.0) — see <https://creativecommons.org/licenses/by-sa/4.0/>

version 1.0, 16-02-2025