


ZIMMERIT DAMAGE to Panther Ausf. G Cuckoo (4th Battalion, Coldstream Guards, October 1944 to February '45)

The grey areas indicate the part covered in Zimmerit, which had chipped off the upper centre area between the machine gun ball mount and driver's periscope, and also from the middle of the left turret side. The area behind where the tube on the left hull side should be, was also clear of Zimmerit.

Drawn to 1:35 scale. For other scales, print out at: —

<i>Scale</i>	<i>Percentage</i>	<i>Document size</i>
1:35	100%	15.5 × 13.0 cm
1:16	219%	33.9 × 28.5 cm (needs A3 paper!)
1:48	72.9%	11.3 × 9.5 cm
1:56	62.5%	9.7 × 8.1 cm
1:72	48.6%	7.5 × 6.3 cm
1:76	46.1%	7.1 × 6.0 cm
1:87	40.2%	6.2 × 5.2 cm

